

Lake Francis MWC
PO Box 422
Dobbins, CA 95935

Work Order: GIF1123

Received: 06/19/26 15:00

Reported: 06/22/26 11:27

System Number: 5800805

Bacteria-Other

Sample Site: 13886 Ingersoll Drive-Other
Sample Number GIF1123-01

Date Collected: 06/19/2026 11:00
Collected by: HAS
Title 22 Designation: Other

	Result	Units	Reporting Limit	Method	Analyst Initials	Analysis Setup Time	Analysis Date
Total Coliform	<1.0	MPN/100 mL	1.0	SM 9223 B - Colilert 18	LS	06/19/26 16:14	06/20/26
E.coli	<1.0	MPN/100 mL	1.0	SM 9223 B - Colilert 18	LS	06/19/26 16:14	06/20/26
Chlorine Residual	ND	mg/L	0.05	Approved Methods	HAS	06/19/26 11:00	06/19/26

Sample Site: 13870 Ingersoll Drive-Upstream-Other
Sample Number GIF1123-02

Date Collected: 06/19/2026 11:14
Collected by: HAS
Title 22 Designation: Other

	Result	Units	Reporting Limit	Method	Analyst Initials	Analysis Setup Time	Analysis Date
Total Coliform	<1.0	MPN/100 mL	1.0	SM 9223 B - Colilert 18	LS	06/19/26 16:14	06/20/26
E.coli	<1.0	MPN/100 mL	1.0	SM 9223 B - Colilert 18	LS	06/19/26 16:14	06/20/26
Chlorine Residual	ND	mg/L	0.05	Approved Methods	HAS	06/19/26 11:14	06/19/26

Sample Site: 13889 Ingersoll Drive-Downstream-Other
Sample Number GIF1123-03

Date Collected: 06/19/2026 11:26
Collected by: HAS
Title 22 Designation: Other

	Result	Units	Reporting Limit	Method	Analyst Initials	Analysis Setup Time	Analysis Date
Total Coliform	<1.0	MPN/100 mL	1.0	SM 9223 B - Colilert 18	LS	06/19/26 16:14	06/20/26
E.coli	<1.0	MPN/100 mL	1.0	SM 9223 B - Colilert 18	LS	06/19/26 16:14	06/20/26
Chlorine Residual	ND	mg/L	0.05	Approved Methods	HAS	06/19/26 11:26	06/19/26

Integrating people, land and water.

1188 East Main Street, Grass Valley, CA 95945

Phone: (530) 273-7284 | Fax: (530) 273-9507 | www.cranmerengineeringinc.com | E.L.A.P. Certification No. 1936

Sampling • Analytical Testing • Courier Service • System Operators • Engineering • Surveying • Technical Reporting • Planning • Construction Mgmt.

Term and Qualifier Definitions

Item	Definition
ND	None detected at or above the reporting limit

Field testing falls outside the scope of laboratory accreditation, and no certification is available for such activities. Accordingly, CEI cannot validate or endorse any field testing results conducted by non-CEI personnel.



Michelle Harlin For Justin Smith
Laboratory Manager

Integrating people, land and water.

1188 East Main Street, Grass Valley, CA 95945
Phone: (530) 273-7284 | Fax: (530) 273-9507 | www.cranmerengineeringinc.com | E.L.A.P. Certification No. 1936
Sampling • Analytical Testing • Courier Service • System Operators • Engineering • Surveying • Technical Reporting • Planning • Construction Mgmt.