

Sample Site: 13882 Shirley Dr

Sample Number GDJ0001-01

Sample Results

Lake Francis MWC PO Box 422 Dobbins, CA 95935 Work Order: GDJ0001

Received: 10/01/21 14:03

Reported: 10/04/21 9:40

System Number: 5800805

Bacteria-Monthly Operator Services

Date Collected: 10/01/2021 11:30

Collected by: GL

Title 22 Designation: Routine

			Reporting	I	Analyst	Bacti Setup	Analysis
	Result	Units	Limit	Method	Initials	Time	Date
Total Coliform	<1.0	MPN/100 mL	1.0	SM 9230 B - 2004 Colilert 18	WES	10/01/21 17:18	10/02/21
E.coli	<1.0	MPN/100 mL	1.0	SM 9230 B - 2004 Colilert 18	WES	10/01/21 17:18	10/02/21
Chlorine Residual	ND	mg/L	0.05	Approved Methods	GL		10/01/21

Term and Qualifier Definitions

Item	Definition
rteiii	Dellillicion

ND None detected at or above the reporting limit

Justin Smith

Laboratory Manager

Integrating people, land and water.



DRINKING WATER SYSTEM CHECKLIST MONTHLY OPERATOR

MONTH/YEAR: 10/2

MUSC System Name: LAKE FRANCIS Operator:

10-1-21

Date: (10) Sign In/Out Times:

Problems/ Comments Any evidence of leaks, vandalism, weeds, security concerns? b) Are the electrical control and junction boxes sealed? **I**tem c) Air release valve/ air volume control operating a) Is the pump at the well operating normally?: c) Is the electrical conduit in good condition? d) Is the sample tap in good condition? b) Casing vent in place & screened Check that the following are OK: b) Water logged or air logged a) No leaks, rusting, damage a) Casing & seal condition Are the following OK? c) Cement slab Due Date if Not Complete Pressure Tank/Bladder Tank ump and Components ¥. a) 🗆 a)□ 밓 $\overset{a)}{\square}$ Visual Inspection å a) a) D Velihead 河 台 Yes a) K CA Da 家 a □ X

1 of 3

Version 1.2 6/24/2011

~
Ξ
ŭ
4
Ñ
õ
_
ď
~
0
S.
4
3
-

MONTHLY OPERATOR DRINKING WATER SYSTEM CHECKLIST

System Name:	ne: しょんち ドクチンコン	3 5
Operator:	6 cars	
Dafe:	(0/1	

MONTH/YEAR: 10/21

Yes	Š	ΑN	Due Date if Not Complete	Item	Problems/ Comments
Storag	Storage Tank				
				Check that the following are OK:	008666 30 h- TEM
(e	Ž.	a		a) No leaks, rusting, damage	wed: 5 06506180
Dia			±.	b) All valves open	
S.				c) Tank support sound	
D P	 	무	5	d) Access port secured	
e)	(e)	e)		e) Vent screened	
	(1836))			Water level ft	-
				Totalizer meter reading:	
Boost	Booster Pump				
□ □ e	= =	a) K		a) Is the pump operating normally?:	
	Qq	垃		b) Are the electrical control and junction boxes sealed?	
밓		c) II		c) Is the electrical conduit in good condition?	
Q	Q Q	D D		d) Is the sample tap in good condition?	
Distril	Distribution System	ystem		I chank that the fallowing are OK:	
Ž.	Ę	Ę		9	
a				a) All sample sites	
DÃ				b) No leaks	
為	밓	0		c) Backflow prevention devices	
			The second secon		

Drinking Water System Operator Checklist MONTHLY

4
-
-
·
α
-
Ч
n
=
10
-
_
2
-
_
-
C
g,
-
a
-
_

MONTHLY OPERATOR

[] []			
System Name: LAKE RANCIS MUC Operator: 18 7.21 Date: Sign In/Out Times:	. Problems/ Comments		
MONTHLY OPERATOR DRINKING WATER SYSTEM CHECKLIST	ltem	a) Any chlorine residual issues based on your review of the log? Raw chlorine specifications	Check that the following are OK: a) Chlorine system secure b) Condition of tubes, hoses and pipes (no leaks) c) Discharge hose condition d) Condition of storage tank
17/0	Due Date if Not Complete		
.R	NA S	X(e	黄黄芪
HWEA	S.	a) —	(a) (b) (b) (c) (d) (d) (d) (d) (d) (d) (d) (d) (d) (d
MONTH/YEAR: 10 (2)	Yes	a)□ a)□ a)Ⅸ	

Drinking Water System Operator Checklist MONTHLY

Sampling conducted in accordance with sampling plans?

Dead ends and sampling locations flushed?